



PRO
COMFORT
ECO

MAX
16
BAR

MAX
232
PSI



AUTO
SCHRADER



SCLAVERAND
PRESTA




DUNLOP

MV EASY

**Leichter
Dichtungs-
wechsel!**

**Easy
sealing
change!**



SCLAVERAND
PRESTA



DUNLOP




AUTO
SCHRADER

EN . RENNKOMPRESSOR NXT DIGI


Professional floor pump with extra long high pressure hose, 120 cm. Cast-iron foot and solid steel tube. Fold up feet for space-saving transport. Digital precision gauge.



Correct folding of the base





Compress the folding foot at the level of the push symbol until it is no longer under the lug of the iron casting base.




Then push the foot upwards until it is in the vertical position.


Handle mounting




Replacement pressure gauge




1. Remove the rubber pad




2. Loosen the Torx screws




3. Loosen the hose screw connection




4. Lift up the pressure gauge cap and turn it away from you




5. Unscrew the pressure gauge at the bottom with an Allen key (10)




6. Insert the pressure gauge into the pressure gauge holder




7. Screw on the pressure gauge with a maximum torque of 2 Nm



8. Put the pressure gauge cap back in place



9. Tighten the Torx screws again



10. Tighten the hose screw connection again


Changing the battery

1. If the battery of the digital manometer is empty, the following symbol appears in the lower right corner.




Please change the battery as follows:

2. Unscrew the two Phillips screws on the underside of the floor pump base.



3. Lift the battery compartment cover off and replace the batteries (2 x 1.5 V AAA). It is imperative that you note the Plus and Minus symbols at the edge of the battery compartment. Insert the batteries so that the plus terminal is placed on the positive side and the minus terminal of the battery is placed on the negative terminal so that the symbols can be seen.



4. Now screw the battery compartment cover back on.
(**CAUTION:** only tighten the screws so that they are hand tight.)